

Previous ADECIA Firmware

version information

V1.0.2

New Functions

When adjusting the effective range of RM-CG tracking in the Web GUI [MICROPHONE SETTINGS], you can now drag and drop the end points (4 orange dots) of each line displayed in the [Tracking area] diagram.

Improvements

Revised the standard for automatic audio tuning.

Fixed Bugs

Fixed the known issue in which the Web GUI "Peripheral Detail / RM-CG" does not function correctly when neither network ports on the rear panel of RM-CR is used.

V1.0.0

Contain VXL1-16P firmware (V1.1.0) for ADECIA Solution.